

HPDE Registration Procedures

1. Arrive at the track early enough to unload (tires, coolers, chairs, etc), hit the bathroom and attend the meeting on time.

2. If you have pre-registered online (i.e. you got a copy of this letter):

-- **and have a signed tech form**, go direct to the **Mandatory** AM driver's meeting, where you will receive your credentials.

-- **but do NOT have a signed tech form**, arrive early and be in line when the gate opens!!! You must take your unloaded car and helmet to tech. After tech, go to the **Mandatory** AM driver's meeting where you will receive your credentials.

HPDE Credentials

All HPDE drivers will need to wear the colored wristband that you receive at the gate in addition to bringing any credentials that you receive at the meeting to grid for each session.

HPDE Tech Forms

Bring the signed [HPDE Tech Form](#) to grid for your first session and place it under your windshield wiper. An official will collect the form and place a group sticker on your windshield.

HPDE Tech Shops

If you are not able to self tech (or don't feel comfortable performing the inspection) and need a shop to perform the inspection, please take advantage of getting it done before the event at one of our recommended [HPDE Tech Shops](#). **At track HPDE inspections are \$20.**

HPDE Parking

We don't do assigned parking, so feel free to grab a spot that works for you. Sometimes grabbing a spot near people with a car similar to yours is a great idea in case you need any help.

HPDE Passengers

Passengers are permitted in HPDE3 (with permission of group leader) and HPDE4. Spins, aggressive driving and off course excursions will result in loss of passenger privileges. Passengers must be at least 18 years of age and sign the passenger waiver at registration. They will need a special passenger arm band –the cost is \$5 and can be obtained from Driver Info.

Rental Helmets

We now have a stock of rental helmets in a variety of sizes available for your passengers.

HPDE Tech Procedures for NASA Rocky Mountain

Your car needs to pass a technical inspection in order to get on the track. Please use the flowchart on the next page to determine your best option.

HPDE / TT TECH FLOW CHART

